












Date: Thursday, 26/07/2007 1:24:44 PM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: BLUE
Job Number	: 33743		
Estimate Number	: 10804		
P.O. Number	: <i>N/A</i>	Part Number	: D29381
This Issue	: 26/07/2007 S.O. No. : <i>N/A</i>	Drawing Number	: D29381
Prsht Rev.	: NC	Project Number	: <i>N/A</i>
First Issue	: <i>N/A</i> Type : SMALL / MED FAB	Drawing Revision	: <i>N/A</i>
Previous Run	: 33742	Material	: <i>N/A</i>
Written By	: <i>[Signature]</i>	Due Date	: 02/08/2007 Qty: 4 Um: Each
Checked & Approved By	: <i>[Signature]</i>		
Comment	:		
Additional Product			
Job Number: 			
Seq. #:	Machine Or Operation:	Description :	
1.0	PACKAGING 1	PACKAGING RESOURCE #1	
			
Comment: PACKAGING RESOURCE #1 PULL FROM STK: 4 X D2938-1UP B <i>32381</i>			
2.0	D29381UP	206 Saddle Left side-unpainted	
			
Comment: Qty.: 1.0000 Each(s)/Unit Total : 4.0000 Each(s) Lug Assembly-unpainted			
3.0	PG	PURCHASING	
			
Comment: PURCHASING PURCHASING ISSUE P.O. <i>4273</i> ATELIER DEBOSSSELAGE SPRAY PAINT DELFLEET BLUE CLEAR DELFLEET <i>u 07-07-27 4</i>			
4.0	PACKAGING 1	PACKAGING RESOURCE #1	
			
Comment: PACKAGING RESOURCE #1 RECEIVE AND INSPECT FOR TRANSIT DAMAGE <i>[Signature] 07/07/30 (4)</i>			
5.0	QC14	INSPECT SPRAY PAINT	
			
Comment: INSPECT SPRAY PAINT <i>[Signature] 07-30 (4)</i>			

Date: Thursday, 26/07/2007 1:24:44 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: BLUE

Job Number: 33743

Part Number: D29381

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
ID & STK USING NEW B/N

1/7/30 (4X) SP

7.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

(4)
20107/31

Job Completion



U 07.07.30